EQUATORIAL GUINEA

NKOA NTOMA CAMP, BATA CITY, LITORAL PROVINCE

IMAGERY ANALYSIS: 09/03/2021 PUBLISHED 10/03/2021

POPULATION 10KM RADIUS	POPULATION 2KM RADIUS	SEVERELY DAMAGED OR DESTROYED BUILDINGS
~300,000	~20,000	243

Inset 1

Inset 2

Inset 3

1km radius zone

2km radius zone

See inset 1 for close-up view

See inset 2 for close-up view

See inset 3 for close-up view

Nkoa Ntoma camp

63 damaged structures in Nkoa Ntoma camp

243 damaged structures

750 structures within 1 km radius

3950 structures within 2km radius

Extensive damage zone

Litoral Province

unitar United Nations Institute for Training and Research

UNOSAT

TECH. DISASTER
AC20210308GNQ



Damage assessment around Nkoa Ntoma camp (SE Bata), Equatorial Guinea

This map illustrates damaged structures in the vicinity of Nkoa Ntoma camp SE of Bata City. 243 structures appear to be heavily damaged or completely destroyed. 750 & 3950 structures are located respectively within 1km and 2km distance from the blast epicenter.

This is a preliminary analysis and has not yet been validated in the field. Please send ground feedback to UNITAR-UNOSAT.

Legend

- Blast epicenter
- Damaged structure
- Nkao Ntamo camp
- 1km radius zone
- 2km radius zone
- Extensive damage zone

Sources

Pre-event satellite image: 19 Feb. 2019
Post-event satellite image: 09 Mar. 2021
Copyright: © CNES (2021), distribution D&S
Source: Airbus D&S
Boundary data: OCHA
Population data: WorldPop
Analysis: UNITAR-UNOSAT
Production: UNITAR-UNOSAT

Map scale for A3: 1:10,000
0 12.5 25 50 Meters

Spatial Reference
Name: WGS 1984 UTM Zone 33N
PCS: WGS 1984 UTM Zone 33N
GCS: GCS WGS 1984
Datum: WGS 1984